









Exhibit 30




File: Figure E2-15.mxd Date: 2/27/2011

Storage Change (acre-feet) / 400 x 400 meters

■ 11 - 50
 ■ 51 - 100
 ■ 101 - 300
 ■ 301 - 500
 ■ > 500
 □ No Change
 ■ -50 - -11
 ■ -100 - -51
 ■ -300 - -101
 ■ -500 - -301
 ■ < -500

WILDERMUTH
 ENVIRONMENTAL INC.
 23692 Bircher Drive
 Lake Forest, CA 92630
 949.420.3030
 www.wildermuthenvironmental.com



Groundwater Storage Change - Gravity Drainage

Antelope Valley, CA

Figure E2-15a