42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

January 31, 2011

Page 1

\$1000.00

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES ©

1/1-31 Received 3 dig alert

1/1-31 Well site check Monday - Friday

1/10 Pull Bacteriological water sample at

-3107 N-3 - passed

1/10 Water Quality Complaint - Cahoon - 3388 W. Avenue N

-see Water Quality Complaint form, completed

-Mrs. Cahoon will call back in 2 weeks if she feels quality is poor

1/10 Repair lock on door of pump house - key stuck in lock

1/10 Locate 3 buried gate valve cans in front of main well site

- 1 valve can needs to be replaced

1/11 Deliver 1 - 24 hour shut off notice - A-3016, Delim

1/11 Spoke with Richard/All Wells - will start on 1/12/11

1/14 Well #1 - 30.2gpm

1/18 Exercise gate valve and flush fire hydrants on 30th St. West

Water Usage

11/30 AVEK reading -4" - 27559400cf 6" - 25248400cf =273,600cf= 2,046,528 gal = 6.3 AF 12/28 AVEK reading -4" - 27559400cf 6" 25274200cf =25,800cf= 192,984 gal = .59af 1/25 AVEK 4" - 27559400cf 6" - 25345900cf =71,700cf= 536,316 gal = 1.6 AF

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

February 28, 2011

Page 1

Bill To: SUNNYSIDE FARMS MUTUAL WATER COMPANY P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437 System #: 1900146 Monthly Maintenance -Per Agreement \$1000.00 24/Hour On-call 2 each - Licensed D2/T2 **FREEBIES®** 2/1-28 Received 3 dig alert 2/1-28 Well site check Monday - Friday Pull Bacteriological water sample at 2/1 -3107 N-3 - passed Secure wood holding electrical meter on well #1 2/3 Anchor building at Well #1 2/3 2/4 Meters Shut off att wells and check booster pumps 2/14 -tank overflowing -booster #2 did not turn on - will call electrician if it happens again 2/19 Chlorinated Well #1 2/21 Weed maintenance at well site Exercise gate valve and flush hydrant on 32nd St. W. 2/28 2/28 Weed maintenance at well sites #1 & #3 Water Usage 12/28 AVEK reading -4" - 27559400cf 6" 25274200cf =25,800cf= 192,984 gal = .59af AVEK reading 4" - 27559400cf 1/25 6" - 25345900cf =71,700cf= 536,316 gal = 1.6 AF3/1 AVEK reading -4" - 27559400cf 6" - 25465200cf =119,300cf=892,364 gal=2.7 AFExtra Labor/Hours® Hours Emergency Call - compressor stuck on 2/27 Extra Labor hours Extra labor charges @\$18.00 /hr 18.00 Parts - repairs on 2/3/11 \$ 16.00

Monthly Maintenance Fee

TOTAL AMOUNT

\$1000.00

\$1034.00

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

March 31, 2011

Page 1 of 2

\$1000.00

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES

3/1-31	Received 1 dig alert
	Well site check Monday – Friday
3/1	Pull Bacteriological water sample at
	-3107 N-3 - passed
3/4	Weed abatement at well site
	Weed abatement at well site
3/8	Unlock and reconnect 3738 W. Ave. N
3/11	Reread 40931 43rd St. W - new read 7207
3/14	Give pump serial # to Roadrunner for bid on booster #1
	pump# 758144A, stamped 114747 - 2693228R
	motor model #050360P3E324TS
3/17	Detail pump house for annual shareholders meeting
3/22	Deliver 2 - 24hours shut off notices - A327, A274
3/22	Call Roadrunner Pumps about booster #1
	-Archie can not find anything to match up
	will send bid to replace booster pump and motor
3/22	Called DRC to see if Red can make a new pump only work
	-Red will meet me tomorrow
3/28	Weed abatement at well site
3/29	Exercise gate valve and flush hydrant on 34th St. W.
3/30	Open gate for USGS to measure well standing level- met during site check n/c
	- 296.18 -well just turned off
	- 288.28 - last year - no well running
3/30	Called All Wells he said he talked to Linda - will blow out next week

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

March 31, 2011

Page 2 of 2

Water Usage

1/25	AVEK reading 4" - 27559400cf	6" - 25345900cf
	=71,700cf= 536,316 gal	= 1.6 AF
3/1	AVEK reading -4" - 27559400cf	6" - 25465200cf
	=119,300cf= 892,364 gal	= 2.7 AF
3/29	AVEK reading -4" - 27559400cf	6" 25563800cf
	=98,600cf= 737,528 gal	= 2.3 af

Extra Labor/Hours®		Hours	
	3/3	Tank overflowing - before hours - #2 booster tripped	1
	3/3	Meet with All Wells - check blowing well and bid for booster #1 replacement	1
	3/4	Meet with All Wells for bid on booster #1 replacement	1
	3/9	Work with Roadrunner Pumps on booster #2 - still tripping	1
	3/22	Pulled required water samples - every three years -GM/IO/GP with asbestos, Nitrates/Nitrites Well #1 & #3	1
	3/24	Meet with Red of DRC Pumps to see if he can replace pump end only on booster #1	1
	3/31	Drop off Lead/Copper bottle at Bob Witts for resample -must bill for shipping next month for this split with SA, iron test	1

TOTAL AMOUNT	\$1183.00
Monthly Maintenance Fee	\$1000.00
Shipping / split with SA - 1/2	\$ 57.00
Extra labor charges @\$18.00 /hr	\$ 126.00
Extra Labor hours = 7	

42107 Quail Creek Drive, Lancaster, Ca 93536 - Office 722-3771 - Fax 722-3799

May 31, 2011

April 30,2011

Water Usage

3/29 AVEK reading -4" - 27559400cf 6" 25563800cf =98,600cf= 737,528 gal = 2.3 AF

4/26 AVEK reading -4" - 27559400cf 6" - 25910100cf =346,300cf= 2,590,324 gal = 7.9 AF

Extra Labor/Hours®

Hours

4

5/20 Install new pressure switch on pressure tank
Install air gap on Well #3 off of pressure relief valve
-corp stop broke off of pressure tower
replaced with brass nipple and cap
cleaned bottom of pressure tower
-2 men XS 2 hours = 4

Extra Labor hours = 4
Extra labor charges @\$18.00 /hr \$ 72.00
Shipping

Monthly Maintenance Fee \$1000.00

TOTAL AMOUNT \$1072.00

42107 Quail Creek Drive Lancaster, Ca93536- Office722-3771* Fax722-3799

May 31, 2011

\$1000.00

Bill To: SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #: 1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES

5/1-31	Received 0 dig alert
5/1-31	Well site check Monday - Friday
5/3	Pull Bacteriological water sample at
	-3107 N-3 - passed
5/4	Record residential water usage
5/2	Weed abatement at well site
5/5	Attempt to flow test meter at 3514 W. Ave. N
	meter read almost 900,000
	- Left note and card - could not enter gate - shut water off
5/5	Restore water service to 3514 W. Ave. N.
	- customer found leak
5/9	Called Red, DRC pumps regarding booster pump
	-pump discontinued, can't match up to old motor
	-will get pearless pump info to get bid+
5/9	Called Roadrunner for bid on booster pump #1
5/9	Called Bakersfield for bid on booster pump #1
5/10	Called Red, DRC with booster pump info
5/16	Order 2 new pressure switches from Blue Book
	- 1 for Booster #2 and 1 for stock
5/17	Exercise valves and flush hydrants on 36th St. W.
5/17	Called Rick, Edison for pump efficiency testing
	-left message
5/17	Dig up and replace valve can in front of well site
5/19	Water theft investigation at 4132 W. Ave. N-3
	- no sign of theft -someone is living there,
5/27	Weed abatement at well site

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

May 31, 2011

\$1000.00

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES

5/1-31	Received 0 dig alert
5/1-31	Well site check Monday – Friday
5/3	Pull Bacteriological water sample at
	-3107 N-3 - passed
5/4	Record residential water usage
5/2	Weed abatement at well site
5/5	Attempt to flow test meter at 3514 W. Ave. N
	meter read almost 900,000
	- Left note and card - could not enter gate - shut water off
5/5	Restore water service to 3514 W. Ave. N.
	- customer found leak
5/9	Called Red, DRC pumps regarding booster pump
	-pump discontinued, can't match up to old motor
	-will get pearless pump info to get bid+
5/9	Called Roadrunner for bid on booster pump #1
5/9	Called Bakersfield for bid on booster pump #1
5/10	Called Red, DRC with booster pump info
5/16	Order 2 new pressure switches from Blue Book
	- 1 for Booster #2 and 1 for stock
5/17	Exercise valves and flush hydrants on 36th St. W.
5/17	Called Rick, Edison for pump efficiency testing
	-left messaage
5/17	Dig up and replace valve can in front of well site
5/19	Water theft investigation at 4132 W. Ave. N-3
	- no sign of theft -someone is living there,
5/27	Weed abatement at well site

42107 Quail Creek Drive, Lancaster, Ca 93536 - Office 722-3771 - Fax 722-3799

May 31, 2011

Water Usage

5/31 AVEK reading -4" - 27559400cf 6"- 26668700cf = 758,600cf 5,674,328 gal = 17.4 AF

4/26 AVEK reading -4" - 27559400cf 6" - 25910100cf =346,300cf= 2,590,324 gal = 7.9 AF

Extra Labor/Hours® Hours

TOTAL AMOUNT

5/20 Install new pressure switch on pressure tank
Install air gap on Well #3 off of pressure relief valve
-corp stop broke off of pressure tower
replaced with brass nipple and cap
cleaned bottom of pressure tower
-2 men XS 2 hours = 4

Extra Labor hours = 4
Extra labor charges @\$18.00 /hr \$ 72.00
Shipping

Monthly Maintenance Fee \$1000.00

4

\$1072.00

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

June 30, 2011

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES

6/1-30 Received 0 dig alert

6/1-30 Well site check Monday - Friday

6/1 Pull Bacteriological water sample at -3107 N-3 - passed

6/2 Record residential water usage

6/7 Reread meters at #3-002 reading is 3444 #3-087 reading is 1140

6/8 Investigate possible water theft at Ave. N west of 36th
-Checked fire hydrant for evidence of water theft-no theft

6/9 Purchase and install new 4" fire hydrant cap at 3718 W. Ave. N

6/9 Purchase and install new 6" gate valve lid

6/14 Exercise valves and flush hydrants on 38th St. W.

6/15 Flow test meter at -40808 38th St. W. - Passed 40830 38th St. W. - Passed

6/16 Deliver 2 - 24 hour shut off notices

6/17 Weed abatement at well site

6/24 Drop off hoist at well site

6/28 Flow test meter at 41034 40th St. W. Lot 3-109 -meter flowed good - horses + plants

\$1000.00

MonisonWeinMainienvince

42107 Quail Creek Drive, Lancaster, Ca 93536 - Office 722-3771 - Fax 722-3799

May 31, 2011

Water Usage

5/31 AVEK reading -4" - 27559400cf 6"- 26668700cf =758,600cf= 5,674,328 gal = 17.4 AF 6/28 AVEK reading -4" - 27559400 6" - 27496600 =827,900cf= 6,192,692gal = 19AF

Extra Labor/Hours⊕			Hour	<u>rs</u>
	6/8	Meet Vonik from AV electrical to see if he can rebuild booster pump head	1	
	6/9	Turn water on at 40831 40th St. W beginning read	i 8680 1	
	6/16	Purchase 2 - 4" blind flanges from HD for #1 booste		
	6/16	Bring generator and jack hammer to 38th & N-8	2	
	0,10	to locate and dig up missing valve cans		
		-found cans and brought to surface		
		- 2 men X 1 hour = 2		
الخر	6/21	Open gate for Rick from Edison for pump efficiency	y test 1	
		on booster #2 and well #3	•	
	6/21	Pull 1/4ly Nitrates as N03 at well #1 & #3		
	6/22	Purchase -	2	
		- 2 - 1.5' comp couplers, 2 - 1.5" couplers, 1 - 10ft -Remove 2nd meter on Bob Witts property	stick 1.5"	
	6/22	Drop off lead and copper bottles to Bob Witts	1	
	6/23	Pick up 3 lead and copper bottles from Bob Witts	1	
	6/24	Pull #1 booster pump head - deliver to AV Electric		
	0/24	2 men X 2 hours = 4		
	6/28	Meet Clinical driver with sample bottles	1	
	0/20	Wilder Chillian arriver with Sample Country	•	
		Extra Labor hours = 15	5	
		Extra labor charges @\$18.00) /hr	\$ 270.00
		Shipping		
		Monthly Maintenance Fee		\$ <u>1000.00</u>
		TOTAL AMOUNT		<u>\$1270.00</u>

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

July August 31, 2011

Extra	Labor/Hours⊗		Hours	
8/17	Pick-up pump from AV Electric booster #1 skid plate	c, unload and drill out broken bolt	2	
8/22 8/30	Work with driller to confirm se Begin installation of booster pu- set pump on skid plate 2 men X 2 hours = 4		1 4	
	Water Usage			
	AVEK reading -4" - 27559400cf =1,112,600cf= 8,322,248 g AVEK reading -4" - 27559400 cf =827,900cf= 6,192,692gal	gal = 25.5AF 6" - 27496600 cf		
		extra Labor hours = 7 extra labor charges @\$18.00 /hr	\$ 1	26.00
		arts - check valve in well	\$	20.00
	N	Ionthly Maintenance Fee	\$ <u>10</u>	00.00
	Т	'OTAL AMOUNT	<u>\$ 11</u>	126.00

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

August 31, 2011

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

\$1000.00

FREEBIES

8/1-31	Received 2 dig alert
8/1-31	Well site check Monday – Friday
8/2	Pull Bacteriological water sample at
	-3107 N-3 - passed
8/3	Record water usage
8/1	Weed abatement at well site
8/4	Reread 4 meters
8/4	shut water off at 4367 W. Ave. N-3, leak - left card
8/4	Reread 3810 W. N-3 - correct 7352
8/9	Reread meter - 3211 W. Ave. N-3 - reading 2280
	-silver dial has very slow movement
8/9	Reread meter - 40946 43rd St. W reading 6170
7/10	Weed abatement at all hydrants and well site
7/12	Film well driller progress
7/12	Called Bill from, All Wells to check on Well #2 progress
	- no answer left message
7/13	Flushed hydrants and exercised gate valves on 40th St. West
7/15	Weed abatement
7/19	Called Archie, Roadrunner Pumps for quote to pull Well #1
	- \$1,070.29
	Called Red, DRC Pumps for quote to pull Well #1
	- \$1,568.66
7/19	Deliver 4 - 24 hour shut off notices
7/27	Weed abatement

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

SUNNYSIDE FARMS MUTUAL WATER COMPANY

Bill To:

August 31, 2011

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437	
System #: 1900146	
Monthly Maintenance -Per Agreement	\$1000.00
24/Hour On-call	4400000
2 each - Licensed D2/T2	
FREEBIES®	
8/1-31 Received 2 dig alert	
8/1-31 Well site check Monday - Friday	
8/2 Pull Bacteriological water sample at	
-3107 N-3 - passed	
8/3 Record water usage	
8/1 Weed abatement at well site	
8/4 Reread 4 meters	
shut water off at 4367 W. Ave. N-3, leak - left card	
8/4 Reread 3810 W. N-3 - correct 7352	
8/9 Reread meter - 3211 W. Ave. N-3 - reading 2280	
-silver dial has very slow movement	
8/9 Reread meter - 40946 43rd St. W reading 6170	
8/11 Move old well #1 pipe to main well site 8/24 Exercise gate valves and flush hydrants on 41st St. W.	
8/24 Exercise gate valves and flush hydrants on 41st St. W.	
Extra Labor/Hours (Hours
8/17 Pick-up pump from AV Electric, unload and drill out broken bolt	2
booster #1 skid plate	2
8/22 Work with driller to confirm second well hole	1
8/30 Begin installation of booster pump #1	4
-set pump on skid plate	
2 men X 2 hours = 4	
Water Usage	
7/26 AVEK reading -4" - 27559400cf 6"- 28609200cf	
=1,112,600cf= 8,322,248 gal $=$ 25.5AF	
8/30 AVEK reading -4" - 27559400 cf 6" - 30039200 cf	
=1,430,000cf= $10,696,400gal = 32.8AF$	
Fretma I altau harren	
Extra Labor hours = 7	m 10.000
Extra labor charges @\$18.00 /hr Parts - check valve in well	\$ 126.00
ratis - check valve in well	\$
Monthly Maintenance Fee	\$1000.00
	\$ <u>1000.00</u>
TOTAL AMOUNT	<u>\$ 1126.00</u>

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

September 30, 2011

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

\$1000.00

\$1000.00

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES®

9/1-30 Received 5 dig alert

9/1-30 Well site check Monday - Friday

Pull Bacteriological water sample at -3107 N-3 - passed 9/7

9/2 Record water usage

9/7 Weed abatement at well site

9/7 Reread 3 meters.

Weed abatement at 30th & Avenue N 9/7

9/8 Weed abatement at well site

9/9 Checked probes on tank

9/14 Meet with Edison

9/14 Clean and seal well head

9/14 Move pipe

9/15 Exercise gate valves and flush hydrants on 42ndt St. W.

Clean pump room 9/16

9/28 Weed maintenance at well site

9/30 Final read for Escrow at 40861 40th St. w. - reading 15

<u>Extra</u>	<u>Labor/Hours®</u>	Hours
9/8	Pull and replace booster pump	4
	2 men X 2 hours = 4	•
9/20	Pull water sample for Nitrates on Well #1 & 3 Pull water sample for TTHMS/Haa5s - 2 sets	1

Water Usage

9/27 AVEK reading -4" - 27559400cf 6"- 30907200cf =868,000cf= 6,484,434 gal = 19.9AF

8/30 AVEK reading -4" - 27559400 cf 6" - 30039200 cf =1,430,000cf=10,696,400gal = 32.8AF

> Extra Labor hours Extra labor charges @\$18.00 /hr 90.00 Parts - Booster #1 anchor bolts 7.83 Monthly Maintenance Fee

> TOTAL AMOUNT \$ 1097.83

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

October 31, 2011

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

\$1000.00

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES

10/1-31 Received 5 dig alert

10/1-31 Well site check Monday - Friday

Pull Bacteriological water sample at -3107 N-3 - passed

10/5 Record water usage

10/17 Weed abatement at well site

10/19 Weed abatement at well site

10/21 Weed abatement at well site

Extra Labor/Hours®

Hours

10/19 Pull water sample for Perchlorates - Well #1 & 3

Pull water sample for TTHMS/Haa5s - 2 sets

Water Usage

Extra Labor hours = 1

Extra labor charges @\$18.00 /hr

18.00

Monthly Maintenance Fee

\$1000.00

TOTAL AMOUNT

<u>\$ 1018.00</u>

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

November 30, 2011

Bill To: SUNNYSIDE FARMS MUTUAL WATER COMPANY P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #: 1900146

Monthly Maintenance -Per Agreement

\$1000.00

24/Hour On-call

2 each - Licensed D2/T2

FREEBIES®

11/1-30 Received dig alert

11/1-30 Well site check Monday - Friday

Pull Bacteriological water sample at -3107 N-3 - passed

11/2 Weed abatement at well site

11/3 Record water usage

Meter leaking from face plate at 11/34011 W. Ave. N-3 - replaced meter Final 307 - New Serial Number 6981715

11/4 Rereads -

Acct #1-010 - 9009 correct

Acct #1-023 - previous 3190 New read 6190

11/11 Adjust AVEK pressure down -overrode our boosters

11/15 Exercise gate valve on 43rd St. West

11/16 Weed abatement at well site

Extra Labor/Hours

<u>Hours</u>

1

11/28 Remove bolts on extra pump head to pull apart from retainer plate - Deliver pump to AV Elec, Vonik for rebuild

11/28 Cover Well hole at 30th & N - All Wells left open

Cover new well hole - at main well site

Water Usage

10/25 AVEK reading

-4" - 27559400 cf 6" - 31537400 cf

=630,200cf= 4,713,896gal = 14.4AF

11/29 AVEK reading

-4" - 27559400cf 6"-31831600cf

=294,200cf= 2,200,616 gal = 6.8AF

Extra Labor hours

Extra labor charges @\$18.00 /hr Monthly Maintenance Fee

TOTAL AMOUNT

<u>\$ 1036.00</u>

\$1000.00

36.00

Thank You For Your Business Happee Holidays

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

December 31, 2011

Page 1 of 2

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

\$1000.00

<u>FREEBIES@</u>

12/1-31 Received 2 dig alert

12/1-31 Well site check Monday - Friday

12/3 Pull Bacteriological water sample at

-3107 N-3 - passed

-pull raw water sample at Well #1

-pull raw water sample at Well #3

11/2 Weed abatement at well site

12/5 Record water usage

12/13 Call Richard with All Wells - no answer - left message

12/15 Mark front of well site for trenching new well

12/15 Call in Dig Alert for well site trenching

12/15 Start to put well #2 back on line - chlorinate

12/15 Exercised gate valves and flushed hydrants on 45th St. West

12/16 Flush and chlorinate well #2

12/27 Turn on compressor

12/27 Chlorinate Well #2

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

December 31, 2011

Page 1 of 2

Extra	<u>Labor/Hours⊗</u>	Hours
12/9	Pull water sample for Nitrates & VOCs on Well #1 & #3	1
12/16	Shut off #2 well for the weekend	
12/19	Flushed well #2 and Pull BacT - failed	1
	-special bact to put #2 well back on line	
12/19	Open well site for Dig Alert to mark site for new well tie in	1
12/20	12/19 bact failed - Chlorinate and Flush Well #2	
12/20	Attempt to raise AVEK pressure	3
	-cla val not responding - call AVEK	
	work with AVEK to trouble shoot cla val problem	
	-switched over to 4" line until 6" can be repaired	
12/21	Chlorinate Well #2 - flush all day	1
12/22	Chlorinate Well #2 - flush all day	1
12/23	Chlorinate Well #2 - flush all day	1
12/27	Pull bacteriological water sample off Well #2	1
	Pull iron water sample off Well #1 - n/c	
2/28	Plumb in Well #2 to new 2" line - new flow meter	8
	-purchase parts at Desert Industrial	
	2 men X 4 hours = 8	

Water Usage

10/25 AVEK reading	-4" - 27559400 cf 6" - 31537400 cf =630,200cf= 4,713,896gal = 14.4AF	
11/29 AVEK reading	-030,200cf 4,713,830gar = 14.4Af -4" - 27559400cf 6"- 31831600cf =294,200cf= 2,200,616 gal = 6.8AF	
	Extra Labor hours = 19	
	Extra labor charges @\$18.00 /hr	\$ 342.00
	New chain for main site & Well #2	\$ 12.26
	Parts for Well #2 flow meter tie in	\$ 214.59
	Monthly Maintenance Fee	\$ <u>1000.00</u>
	TOTAL AMOUNT	<u>\$ 1568.85</u>

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

January 31, 2012

Page 1 of 2

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146

Monthly Maintenance -Per Agreement

24/Hour On-call

2 each - Licensed D2/T2

\$1000.00

FREEBIES

11 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1/	1	-31	Received	1	dig	alert
--	----	---	-----	----------	---	-----	-------

- 1/1-31 Well site check Monday Friday
- 1/3 Pull Bacteriological water sample at -3107 N-3 passed
- 1/6 Record water usage
- 1/10 Deliver 3 24 hour shut off notices -Acct# 1-007, 3-016, 3-022
- 1/11 Disconnect and lock Acct#1-007
- 1/23 Called Richard with All Wells for electric tie in and flow meter price
- 1/23 Complete and fax per DPH request -ENP Emergency Notification Plan
- 1/18 Exercise gate valves and flush meters on 30th St. W.
- 1/20 Weed abatement at well site
- 1/26 Lock off 3738 W. Ave. N Final read 4103
- 1/26 Mark gate valves at 40th St. W. and Ave. N
- 1/26 Turn on Well #1
- 1/27 Measure for wire needed at main well site to fit in electrical for both well
 - 70' from well #4 to well#5
 - 200' feet from future well to front of electrical panel

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

January 31, 2012

Page 1 of 2

Extr	a Labor/Hours®	<u>Hours</u>
1/1	Emergency call - 3738 W. Ave. N - shut off water -homeowner not home - left note - 7 am	1.5
1/5	Fill in trench at well site from Chlorinating and flushing Well #2	2
1/9	-2 men x 1 hour = 2 Trench line for new well - Well #4	7
1/10	-2 men X 3.5 hours = 7 Order saddle clamp at HD - glue together pipe for well fill line	3
1/20	-2 men X 1.5 = 3 Go to HD for two flow meters for both wells	1.5
1/22	-Open well site for Cliff from HD to bid proper meter Tank overflowing - turn off all well - Sunday call	1.5
~, ~~		- 70

Water Usage

1/31 AVEK reading

-4" - 27687900 cf 6" - 31913600 cf =000,000cf= 0,000,000gal = 00.0AF

Extra Labor hours = 16.5	
Extra labor charges @\$18.00 /hr	\$ 297.00
Parts - Well #4 - ck valve + misc parts	\$ 193.91
Parts - Well #2 paint supplies pump house	\$ 23.79
Monthly Maintenance Fee	\$ <u>1000.00</u>
TOTAL AMOUNT	<u>\$ 1514.70</u>

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

SUNNYSIDE FARMS MUTUAL WATER COMPANY

Bill To:

February 29, 2012

Page 1

	P.O. BOX 90.	1025, Palmdale, CA 93590 - 661-947-3437		
System #:				
Monthly Maintenance -Per Agreement 24/Hour On-call 2 each - Licensed D2/T2			;	\$1000.00
rorroi	_	censeu D2/12		
FREEBI	-29 Received	1 dia alam		
		1 dig alert aeck Monday – Friday		
2/1		ological water sample at		
24 1	-3107 N-3 -			
2/3 Record water usage				
2/1		tenance at main well site		
2/6	Weed main	enance at well #2		
2/7		tenance at main well site		
		enance at main well Site		
	2/15 Remove trash and debris from Well #2			
	2/17 Weed abatement at main well site			
2/20 Weed abatement at well #3 2/20 Drain pressure tank at well #3				
		ure tank at well #3		
212	2/29 Exercise gate valves and flush fire hydrants on 32nd St. Wriser cans needed at N-3 & 32nd / N-8 & 32nd			
	11501 Guils I	11-5 to 32/10 / 11-6 to 32/10		
Extra Lab	oor/Hours⊗		<u>Hours</u>	
2/1	Paint pump	house at 30th St. W. & Avenue N	4	
2/15		ster pump motor	1	
	_	•		
Water Usa	age			
2/28 AVE	K reading	-4" - 27799500 cf 6" - 31913600 cf =000,000cf= 0,000,000gal = 00.0AF		
		Extra Labor hours = 5		
		Extra labor charges @\$18.00 /hr		\$ 90.00
		Monthly Maintenance Fee		\$ <u>1000.00</u>
manage "		TOTAL AMOUNT		<u>\$ 1090.00</u>

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

March 31, 2012

Page 1 of 2

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146 - Monthly Maintenance -Per Agreement

\$1000.00

24/Hour On-call - 2 each - Licensed D2/T2

FF

REI	EBIES	☺
	3/1-31	Received 6 dig alert
	3/1-31	Well site check Monday - Friday
	3/12	Pull Bacteriological water sample at -3107 N-3 - passed
	3/2	Record water usage
	3/5	Weed maintenance at main well site
	3/8	Weed maintenance at well #2
	3/9	Weed maintenance at main well site
	3/9	Clean out pump room
	3/14	Weed maintenance at Well site #3main well Site
	3/15	Weed maintenance at Well site #3
	3/19	Check w/ Northern Tools for oil less compressor - none
	3/19	Get price from HD for oil less compressor - same as blue book
	3/19	Call All Wells for wiring of Well #4 - says will be in today
	3/19	Call Road Runner Pumps for price to install new compressor
	3/19	Replace meter box at 41112 36th St. W
	3/22	Call AV Electric to get rebuild cost
	3/22	Call Accurate Air for 3 phase compressor - see price sheet
	3/30	Weed abatement at well site #3
	3/28	Weed abatement at well site

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

March 31, 2012

Page 2 of 2

Extra Labo	r/Hours⊗	Hours
3/5	Complete fire flow form for 40913 40th St. W.	1
3/5,6,7,8	Complete monthly usage spread sheet	8
3/11	Emergency shut off/on - Sunday call at 41049 43rd St. W.	2
3/13	Pull Nitrates and Iron sample from Well #1 & #3	1
3/19	Meet w/ All wells to go over wire set up	1
3/19	Dig up and clean around gate valve in front of pressure tank	1
	-shut down valve-compressor down/tank water logged-will drain	
3/21	Meet w/ USGS to sound Well #3 -static water level 285.19	1
3/21	Turn water on and complete walk-through inspection at	1
	-4232 W. Avenue N	
3/28	Remove compressor and deliver to Vonic/AV Elec for rebuild	2

Water Usage

110000			
2/28 AVEK reading	-4" - 27799500 cf	6" - 31913600 cf	-
3/28 AVEK reading	-4" - 28159600 cf	6" - 31913600 cf	F
_	360,100cf =	2,693,548gal = 8.3 A	۱F

TOTAL AMOUNT	<u>\$1324.00</u>
Extra labor charges @\$18.00 /hr Monthly Maintenance Fee	\$ 324.00 \$ <u>1000.00</u>
Extra Labor hours = 18	

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

April 30, 2012

Page 1 of 2

Bill To: SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #: 1900146 - Monthly Maintenance -Per Agreement

\$1000.00

24/Hour On-call - 2 each - Licensed D2/T2

FREEBIES@

	Received 3 dig alert
	Well site check Monday – Friday
4/3	Pull Bacteriological water sample at -3107 N-3 - passed
4/2	Weed maintenance at well #2, #3 & #1
4/4	Weed maintenance at main well site
4/5	Record residential water usage - meters
4-6	Replace meter box lid at 4229 W. Ave. N-8
4/9	Called Vonik regarding rebuild on compressor, cannot rebuild.
4/9	Review compliance report - compile list
4/9	Call BWP for price on compressor
4/9	Weed maintenance at Well site #1, #2 & #3
4/12	Purchase case of marker paint and mark all of 30th, N and 45th St. W.
4/12	Weed abatement at Well site #2
4/13	Water quality complaint at 4002 W. Ave. N-3
	-water rusty -old galvanized pipe & gas pipe rusting
4/16	Exercise gate valves and flush hydrants on 36th St. W.
4/16	Called Vonik on compressor
	- he can't find anyone for the job
4/16	Called BWP - left message - no call back
4/16	Weed abatement at well site #1, #2 & #3
4/25	Sealed cracks in concrete slab on #3 well
4/25	Weed maintenance at main well site

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

April 30, 2012

Page 2 of 2

<u>Extra I</u>	Hours			
 4/12 Removed tree away from well - dig around well 6" deep 4/18 Sealed building at well #1, free of gaps and holes -Anchored building, fill holes with spray foam and install sheet metal and wood and purchased supplies 2 men X 3 hours = 6 hours 				2 6
		e-install door at #3 pump he	ouse Well Site #2	3
	and purchase supplies Install flow meter at V			2
<u>Water</u> 3/28 A	<u>Usage</u> VEK reading	2/28 AVEK reading -4" - 28159600 cf 6' 360,100cf = 2,693,5	-4" - 27799500 cf " - 31913600 cf 548gal = 8.3AF	6" - 31913600 cf
		Extra Labor hours Extra labor charge Repairs/supplies Repairs/supplies for Monthly Maintena	s @\$18.00 /hr on Well #2 shed or threshold	\$ 234.00 \$ 22.05 \$ 50.60 \$1000.00
		TOTAL AMOUN	NT	<u>\$1306.65</u>

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

May 31, 2012

Page 1 of 2

Bill '	To:	SUNNYSIDE FA	RMS MUTUAL	WATER COMPANY	
		P.O. BOX 901025, P	almdale, CA 93590 -	661-947-3437	
System #:		1900146 - Monthly Maintenance -Per Agreement			\$1000.00
		24/Hour On-call	- 2 each - Licens	sed D2/T2	
FRI	EEBIES	3			
	5/1-31	Received 3 d	ig alert		
	5/1-31	Well site check M	londay – Friday		
	5/2	Pull Bacteriologic	al water sample a	t -3107 N-3 - passed	
	5/3	Detail well site - v	weed maintenance	;	
	5/4	Unlock and recon	nect 3738 W. Ave	e. N	
	5/4	Weed maintenand	e at well #2 & #3		
	5/7	Reread meter at 4	0815 30th - read i	s 4628	
	5/10	Weed maintenanc	e at well site #2		
	5/11	Weed maintenand	e at main well site	e	
	5/14	Weed maintenand	e at well site		
	5/24	Turn off water pe	r owner at 3445 V	V. Ave. N-3 - read is 256	7
	5/22	Exercise gate valv	e and flush hydra	ints on 38th St. W.	
		Both cans for ma	inline valves on 3	8th & N-8 need to be rep	laced
		valve can guide p			
	5/30	Turn water on at 3	3445 W. Ave. N-3	}	
		peginning read is	2567		
	5/30	Pressure tank blov	wing off - AVEK	over-pressurized system	
		Called AVEK, the	ey said they would	d fix pressure issue	
Evtr	a Labor/	[aure@			ITonna
LXU	<u>a Labui7</u> 5/6		Wells called aski	ng for access to the	<u>Hours</u> 1.5
	5/0			porary compressor	1.3
		_		the pressure tank could be	••
		drained and storage			DE .
	5/10	Sealed building at		dunday Can	1
	5/10	painted door on p		oured building	1
	5/19	Low pressure call			1 1 5
	3/17	pressure at well s	-	Jui & 19-0	1.5
		pressure at custo		Saturday call	
	5/31			pressure - set at 64psi	1
Wat	er Usage	AN OLK ANTHU VA A TOP	Lio scio Cia-vai	pressure - set at 04psi	1
YYAL	er Usage	5/29 AVE	K reading	-4" - 29717000 cf	6" - 31913600 cf
3/29	AVEK re		' - 28159600 cf		0 - 21212000 C1
2120	1 7 A 1717 1C	ming -4	- 20139000 01	0 - 21312000 01	

Extra Labor hours = 6
Extra labor charges @\$18.00 /hr \$ 108.00
Monthly Maintenance Fee \$\frac{1000.00}{51108.00}\$

000cf = 0gal = 0AF

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

June 30, 2012

Page 1 of 2

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146 - Monthly Maintenance -Per Agreement

\$1000.00

24/Hour On-call - 2 each - Licensed D2/T2

FREEBIES®

6/1-30	Received 4 dig alert
6/1-30	Well site check Monday - Friday
6/4	Pull Bacteriological water sample at -3107 N-3 - passed
6/5	Record water usage - meters
6/7	Additional BacT at holding tank
6/7	Flush pressure tank until there was a Cl2 residual
6/7	Replace pressure tank guage
6/7	Reread 40815 30th St. W - missing a digit - read 4667
6/8	Meet with Richard, All Wells regarding compressor
6/8	Attempted to get compressor on line
6/8	Weed abatement at main well site
6/14	Investigate dirty water at 41049 43rd St. W.
	-water is clear now
	-Toilet tank still full of rusty debris
6/15	Tear apart flow meter on Well #3 to flush off
	-fuses were not in mag starter so well would not run
	-call All Wells on Monday
6/15	Called Rick/Edison for pump efficiency test
6/15	Flushed #2 Well for 15 minutes
6/18	Weed maintenance at well site

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

June 30, 2012

Page 2 of 2

Extra Labor	<u>Hours</u>		
6/11	1		
6/11	-chlorinate each well Start to test system - back on line -compressor pressure switch set to low	1	
6/18	Hand dig around well #3, #4well & #5well electric panels 4 hours X 3 men = 12	12	
6/20	Trench at well site for water line on well #5 - 2 men X 3.5 = 7	7	
6/25	Continue to dig trench for power line 2 men X 3 hours = 6	6	
6/26 6/27	Continue to dig trench for power line -2 men X 4 hours=8 Lay pipe and back fill trench	8 9	
6/27	3 men X 3 hours = 9 t Pull Nitrate samples on #1 & #2 wells	_1	
	TOTAL EXTRA LABOR	45	
Water Usage			
5/29 AVEK r	eading 4" - 29717000 cf 6" - 31913600 cf		
6/26 AVEK r	eading 4" - 29791200 cf 6" - 32762000 cf		
	922,600cf = 6,901,048gal = 21.1AF		
	Extra Labor hours = 45 Extra labor charges @\$18.00 /hr Parts - Equipment Fuel - Back hoe Monthly Maintenance Fee	\$ 810.00 \$ 89.08 \$ 21.52 \$ <u>1000.00</u>	} ?
	<u>\$1920.60</u>	į	

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

July 31, 2012

Page 1 of 2

Bill To: SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #: 1900146 - Monthly Maintenance -Per Agreement

24/Hour On-call - 2 each - Licensed D2/T2

\$1000.00

FREEBIES

7/1-31	Received 4 dig alert
7/1-31	Well site check Monday – Friday
7/3	Pull Bacteriological water sample at -3107 N-3 - passed
7/3	Record water usage - meters
7/5	Lovejoy coupling wore out on booster #1 - turned off all wells
7/7	Tank overflowed - well #2 still on - turned #2 off
7/10	Deliver 2 - 24 hour shut off notices - acct 1-056, 3-012
7/11	Meet with All Wells to go over connections on Well #2
	-so he can get Well #5 wired in
7/16	Weed maintenance at Well #2
7/23	Weed maintenance
7/24	Flush hydrants and exercise gate valves on 40th St. W.
7/25	Water quality complaint at 40932 40th St. W brown/dirty water
	-flushed both hydrants between N-3 & N-8 on 40th St. W.
	-North hydrant was clear right away
	-customer gate was locked - could not check water on property
7/30	Well not sounding right - electrical panel smells burnt - checked twice
	-pump saver was hot - called All Wells to troubleshoot
7/31	All Wells called said it was Edison - power was fluctuating
	-reset panel to handle power fluctuation
7/31	Turn water off at 4057 W. Ave. N-3 - FINAL 611

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

July 31, 2012

Page 2 of 2

Extra Labor/Hours®					
7/2 7/10 7/13	Back filled	d power line trench by ele	vater line to main from Well #5 - well not connected ower line trench by electrical panels - by hand replace Lovejoy on booster #1		
		ТОТА	AL EXTRA LABOR	7	
Water Usage	<u> </u>				
7/31 AVEK r	eading	4" - 30395400 cf	6" - 33496600 cf		
6/26 AVEK r	eading	4" - 29791200 cf	6" - 32762000 cf		
<u> </u>		1,338,800cf =	10,041,224gal = 30.7AF		
		Parts - vents Parts - 7/2 re	harges @\$18.00 /hr Well #2 pump house pair	\$ \$	26.00 23.86 3.60
		Monthly Ma	intenance Fee IOUNT		000.00 153.46

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

August 31, 2012

Page 1 of 2

Bill To:		SUNNYSIDE FARMS MUTUAL WATER COMPANY					
		P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437					
System :	#:	1900146	\$1000.00				
			On-call - 2 each - Licens				
FREE	BIES	<u> </u>					
			0 dig alert				
			check Monday - Friday				
	/1	Pull Bacte	eriological water sample a	t -3107 N-3 - passed			
	/3		ater usage - meters				
	/8		er on at 4057 N-3 - beg R				
	/8		locations of 4/5 wells & s	send to office			
	/9		air vents for building				
8	/14	Run chlor	inated water at 65psi for 1 tube flowed clearly	0 minutes down well #5			
8	/15	Run water	r down sounding tube for	Well #4			
_		-Flushed f	for 15 minutes, water neve	er surfaced -no clog			
_~ 8	/27		l#1 back on				
;)		-make sure boosters are running properly					
			Weed maintenance at Well 1, 2 & 3				
8	/28	Flush hyd	rants and exercise gate va	lves on 42nd St. W.			
Extra La	abor/J	Hours⊗			<u>Hours</u>		
	/2		n Rick from Edison on pur	mp efficiency test Well 1,	2,3 2		
			TOT	AL EXTRA LABOR	2		
<u>Water U</u>	sage						
7/31 AV	EK re	ading	4" - 30395400 cf	6" - 33496600 cf			
8/28 AVEK re		ading	4" - 31322200 cf	6" - 33557200 cf			
				987,400cf = 7,385,73	52gal = 22.7AF		
			Extra Labor l				
				harges @\$18.00 /hr	\$ 36.00		
		Parts - Monthly Maintenance Fee			\$ 0.00		
			\$ <u>1000.00</u>				
			TOTAL AM	OUNT	<u>\$1036.00</u>		

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

September 30, 2012

Page 1 of 2

Bill To:	SUNNYSIDE FARMS MUTUAL		
Character II	P.O. BOX 901025, Palmdale, CA 93590 - 0		
System #:	1900146 - Monthly Maintenance -Per	_	\$1000.00
	24/Hour On-call - 2 each - License	ed D2/T2	
<u>FREEBIE</u>			
9/1-3			
9/1-3			
9/4	Pull Bacteriological water sample at	-3107 N-3 - passed	
9/5	Record water usage - meters		
9/6	Replace meter, no movement, at 436	7 W. Ave. N-3	
016	New serial number 6981719 - FINA		
9/6	Reread 40931 40th - correct REAI		
Tretus I also	Reread 3445 W. Ave. N-3 - correct	READ 2575	
Extra Labor 9/4		NT\$44	Hours
9/ 4 9/27	Pull sample for TTHMS/Haa5s and I	Nitrates on all wells	1
9121	Emergency service line break at 409 2 men X 4 hours X 1.5 = 12	912 34th St. W.	12
9/26	Repair leaking drain line on booster	#1	2
7/20	Repair love joy coupler -Love joy bo		2
market T	-move back in place and mark to che	ouncing	
	parts donated by Morrison Well Mai	ntenance	
9/28	Purchase coupling and repair leak at	40012 34th St W	4
5,20	Backfill open remaining valves	40)12 34ul St. W.	4
	2 men X 2 hours = 4		
		L EXTRA LABOR	19
Water Usage		a Dillini DABOK	17
8/28 AVEK 1		6" - 33557200 cf	
9/25 AVEK 1	eading 4" - 32020000 cf	6" - 33557200 cf	
	= 16.0 AF		
	\$ 342.00 \$ 6.63		
	\$ 25.49		
	\$ <u>1000.00</u>		
	<u>\$1374.12</u>		

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

October 31, 2012

Page 1 of 2

Bill To:

SUNNYSIDE FARMS MUTUAL WATER COMPANY

P.O. BOX 901025, Palmdale, CA 93590 - 661-947-3437

System #:

1900146 - Monthly Maintenance -Per Agreement

\$1000.00

24/Hour On-call - 2 each - Licensed D2/T2

FREEBIES®

10/1-31 Received 5 dig alerts

10/1-31 Well site check Monday - Friday

10/2 Pull Bacteriological water sample at -3107 N-3 - passed

10/5 Record water usage - meters

10/22 Deliver 1 - 24 hour shut off notice to 40810 46th St. West

10/29 Weed abatement Well #1

10/29 Flushed hydrants on N between 30th and 45th St. West

10/29 Flushed all hydrants on N-3

10/30 Customer request shut off at 40935 36th St. West -located gate valve for customer, left water on

10/30 Customer requested water turned back on at 40935 36th St. West -water already on, our side - turned his gate valve on, was closed

Extra Labor/Hours®

None @

<u>Hours</u>

TOTAL EXTRA LABOR

Water Usage

9/25 AVEK reading

4" - 32020000 cf

6" - 33557200 cf

10/30 AVEK reading

4" - 32577400 cf

6" - 33557200 cf

557,400cf = 4,169,352gal = 12.8 AF

Extra Labor hours = 0

Extra labor charges @\$18.00 /hr \$ 0.00
Parts - coupler for repair \$ 0.00
Parts - coupler for stock in shed \$ 0.00
Monthly Maintenance Fee \$1000.00

TOTAL AMOUNT

\$1000.00

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

SUNNYSIDE FARMS MUTUAL WATER COMPANY

Bill To:

November 30, 2012

Page 1

		P.O. BOX 90102	25, Palmdale, CA 935	90 - 661-947-3437				
System #	: :	1900146 - Monthly Maintenance -Per Agreement 24/Hour On-call - 2 each - Licensed D2/T2					\$1000.00	
FREEB	IES	<u> </u>						
		Received 4	_					
			eck Monday – Frid					
			ogical water samp	le at -3107 N-3 -	· passed			
			usage - meters ved- turn off outer	11-				
			ved- turn off officer valves and flush h		C+ W7			
			pressure at vaults		SL. W.			
1.7	.,		ng our boosters					
			J					
Extra La	bor/l	<u>Hours⊗</u>				Hours		
11	1/7	Calculate amount of piping in system using schematics				2		
met property		6" pvc line 4.5 miles						
		8" pvc line						
11	1/27	Emergency sh	ut off at 40840 3	2nd St. W.		1		
			Te	OTAL EXTRA	LABOR	3		
Water U	sage							
			4" - 32577400 cf					
11/27 AV	ÆK r	eading	4" - 32898900 cf	6" - 3355	7200 cf			
				321,400cf =	2,404,072gal	= 7.4 AF		
				,				
			Extra Lab	oor hours =	3			
			Extra lab	or charges @\$18	3.00 /hr		\$ 54.00	
			Parts -				\$ 0.00	
			Monthly !	Maintenance Fe	e		\$ <u>1000.00</u>	
			TOTAL	AMOUNT			\$1054.00	

Thank You For Your Business

We Wish You and Your Families the Happiest of Holidays

42107 Quail Creek Drive Lancaster, Ca 93536 - Office 722-3771 * Fax 722-3799

December 31, 2012

Page 1

Bill To		CHANVEIDI	T DADMS MITTILL	L WATER COMPANY	
DIII 10.		P.O. BOX 9010			
System #:			onthly Maintenance -Per		\$1000.00
Ü			call - 2 each - Licen	· ·	#1000.00
FREE	BIES	<u>s@</u>			
		1 Received 4	_		
			eck Monday – Friday		
	12/4	Pull Bacteriol	logical water sample a	at -3107 N-3 - passed	
	12/4	Record water	usage - meters		
	12/7	Flushed Well	#4 & #5		
•	12/7	Weed abatem	ent		
			c at 38th & N-3 - turn		
•	12/28		valves and flush hydr		
		-valve on N-3	& 45 only turn 9 tim	es than seizes	
_Extra I	abor/	Hours⊗			Hours
3	12/4		ater samples from wel	11 #1. #2 & #3	110u15
<u> </u>	12/5		ow engineering to she		1.5
		and system w			
•	12/10	Pull Nitrates	on Well #1, 2 & 3 - no	shipping charges	1
	TOTAL EXTRA LABOR			3.5	
Water	Heere				
		reading	4" - 32898900 cf	6" - 33557200 cf	
		reading	4" - 32901900 cf		
1,2,101		10441116	. 32,01,0001	0 - 33337200 CI	
			30	000 cf = 22400 gal = .0	07AF
				J	
			Extra Labor	harre - 25	
				- · · ·	<u> </u>
			Parts -	charges @\$18.00 /hr	\$ 63.00 \$ 0.00
				intenance Fee	*
			manual in the second se	intologico I oc	\$ <u>1000.00</u>

<u>\$1063.00</u>

TOTAL AMOUNT