


Exhibit 38




Produced by:

WILDERMUTH
ENVIRONMENTAL INC.
23692 Birtcher Drive
Lake Forest, CA 92630
949.420.3030
www.wildermuthenvironmental.com

Author: WEL

Date: 20100624

File: E2-16_Subsidence.mxd



Total Subsidence 1930 to 1992

Antelope Valley Groundwater Basin

Figure E2-16

PhelanCSD-38, Page 000001