



# **Exhibit 30**

1951 - 62




Storage Change (af): -3,229,000

1963 - 70




Storage Change (af): -1,221,000

1971 - 78




Storage Change (af): -361,000

1979 - 84




Storage Change (af): 32,000

1985 - 91




Storage Change (af): 25,000

1992 - 97




Storage Change (af): 210,000

1998 - 05



Storage Change (af): -485,000

2006 - 09



Storage Change (af): -153,000

Storage Change (acre-feet) / 400 x 400 meters

11 - 50 51 - 100 101 - 300 301 - 500 > 500 No Change -50 - -11 -100 - -51 -300 - -101 -500 - -301 < -500

**WILDERMUTH**  
ENVIRONMENTAL INC.  
23692 Birtcher Drive  
Lake Forest, CA 92630  
949.420.3030  
www.wildermuthenvironmental.com



0 10 20 30 40 Miles

**Groundwater Storage Change - Gravity Drainage**

Antelope Valley, CA

Figure E2-15a